

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start		Rating **	M	Issue No.	38
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0536_01_s_2012_38				
Action/Comments					
Inspector Comments: The District does not have a staff only land owners.					

No Photos

LM Start		Rating **	M	Issue No.	39
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0536_01_s_2012_39				
Action/Comments					
Inspector Comments: District needs to get a copy of the O&M manual.					

No Photos

LM Start		Rating **	M	Issue No.	40
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0536_01_s_2012_40				
Action/Comments					
Inspector Comments: The district should keep a supply of floodfight materials.					

No Photos

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	0.03	Rating **	M	Issue No.	21
LM End	1.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245012 °	38.259667 °
				-121.768460 °	-121.749812 °
DWR ID	DWR_RD0536_01_f_2014_21				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	0.03	Rating **	A/W	Issue No.	24
LM End	1.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245012 °	38.259667 °
				-121.768460 °	-121.749812 °
DWR ID	DWR_RD0536_01_f_2014_24				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: At this location there is no problem with the vegetation.					

Photo 1 of 1 : FA_2014_RD0536_208_24_20141107_00016.jpg



Looking downstream from levee mile 0.02 landside slope.

LM Start	0.67	Rating **	M	Issue No.	7
LM End	0.98	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.249615 °	38.253717 °
				-121.760165 °	-121.757979 °
DWR ID	DWR_RD0536_01_f_2014_7				
Action/Comments					
Inspector Comments: 2011 - Multiple sections of slumping bank. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: LDS_0-6_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	0.93	Rating **	M	Issue No.	27
LM End	4.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.250750 °	38.248661 °
				-121.749210 °	-121.717443 °
DWR ID	DWR_RD0536_01_s_2012_27				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	0.95	Rating **	M	Issue No.	41
LM End	1.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.253287 °	38.259667 °
				-121.757937 °	-121.749812 °
DWR ID	DWR_RD0536_01_f_2014_41				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	1.10	Rating **	U	Issue No.	25
LM End	1.10	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.255455 °	38.255455 °
				-121.757587 °	-121.757587 °
DWR ID	DWR_RD0536_01_s_2014_25				
Action/Comments					
Inspector Comments: This gate looks like its been run over, the bottom hinge is broken thus making the gate hard to open and close properly.					

Photo 1 of 1 : FA_2014_RD0536_208_25_20141030_00002.jpg



This gate needs to be replaced.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	1.16	Rating **	M	Issue No.	34
LM End	4.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.256246 °	38.248888 °
				-121.757581 °	-121.718091 °
DWR ID	DWR_RD0536_01_s_2014_34				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	1.19	Rating **	U	Issue No.	43
LM End	1.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.256722 °	38.258655 °
				-121.757558 °	-121.757393 °
DWR ID	DWR_RD0536_01_f_2014_43				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the tall weeds from the landward levee slope.					

Photo 1 of 1 : FA_2014_RD0536_208_43_20141107_00018.jpg



Tall weeds on landside slope and toe of levee section.

LM Start	1.27	Rating **	M	Issue No.	8
LM End	3.74	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.257888 °	38.251710 °
				-121.757461 °	-121.726261 °
DWR ID	DWR_RD0536_01_f_2012_8				
Action/Comments					
Repair depressions or ruts in the crown or slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	1.34	Rating **	M	Issue No.	47
LM End	1.55	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.258930 °	38.258637 °
				-121.757085 °	-121.753397 °
DWR ID	DWR_RD0536_01_f_2014_47				
Action/Comments					
Add appropriate material and re-grade the levee to bring the crown above the design elevation.					

No Photos

LM Start	1.34	Rating **	U	Issue No.	45
LM End	4.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.258860 °	38.248497 °
				-121.757142 °	-121.717193 °
DWR ID	DWR_RD0536_01_f_2014_45				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Unwanted wild growth of weeds and wild roses growing on the waterward levee slope.					

Photo 1 of 1 : FA_2014_RD0536_208_45_20141107_00019.jpg



Wild growth of wild roses present on waterside slope and toe.

LM Start	1.42	Rating **	U	Issue No.	48
LM End	1.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.259203 °	38.258757 °
				-121.755698 °	-121.753883 °
DWR ID	DWR_RD0536_01_f_2014_48				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: The landward levee slope is covered in wild weeds and star thistle.					

Photo 1 of 1 : FA_2014_RD0536_208_48_20141107_00020.jpg



Unwanted star thistle on shoulder landward downstream to levee mile 1.52

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	1.59	Rating **	U	Issue No.	49
LM End	1.74	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.258792 °	38.259777 °
				-121.752675 °	-121.750418 °
DWR ID	DWR_RD0536_01_f_2014_49				
Action/Comments					
Keep the crown roadway free of vegetation.					
Inspector Comments: Crown roadway should be kept free of vegetation.					

Photo 1 of 1 : FA_2014_RD0536_208_49_20141107_00021.jpg



Unwanted grasses present on crown roadway.

LM Start	1.61	Rating **	M	Issue No.	50
LM End	1.66	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.259120 °	38.259593 °
				-121.752229 °	-121.751689 °
DWR ID	DWR_RD0536_01_f_2013_50				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	1.72	Rating **	M	Issue No.	14
LM End	1.76	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Cracking			38.259846 °	38.259735 °
				-121.750813 °	-121.749959 °
DWR ID	DWR_RD0536_01_s_2012_14				
Action/Comments					
Monitor and have inspected by geotechnical engineer.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.05	Rating **	M	Issue No.	59
LM End	2.05	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.257917 °	38.257917 °
				-121.746789 °	-121.746789 °
DWR ID	DWR_RD0536_01_s_2014_59				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	2.14	Rating **	M	Issue No.	53
LM End	2.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.257972 °	38.257972 °
				-121.745090 °	-121.745090 °
DWR ID	DWR_RD0536_01_f_2014_53				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	2.15	Rating **	M	Issue No.	60
LM End	2.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.257966 °	38.257966 °
				-121.744912 °	-121.744912 °
DWR ID	DWR_RD0536_01_s_2014_60				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.18	Rating **	C	Issue No.	23
LM End	2.19	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.258019 °	38.258093 °
				-121.744444 °	-121.744052 °
DWR ID	DWR_RD0536_01_f_2012_23				
Action/Comments					
Add appropriate material and re-grade the levee to bring the crown above the design elevation.					

No Photos

LM Start	2.26	Rating **	M	Issue No.	26
LM End	2.26	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.258345 °	38.258345 °
				-121.742915 °	-121.742915 °
DWR ID	DWR_RD0536_01_f_2012_26				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	2.31	Rating **	M	Issue No.	54
LM End	2.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.258553 °	38.258553 °
				-121.742088 °	-121.742088 °
DWR ID	DWR_RD0536_01_f_2013_54				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.49	Rating **	M	Issue No.	30
LM End	2.49	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.257663 °	38.257663 °
				-121.739072 °	-121.739072 °
DWR ID	DWR_RD0536_01_f_2012_30				
Action/Comments					
Add appropriate gravel or road base. Grade and compact.					

No Photos

LM Start	2.54	Rating **	C	Issue No.	61
LM End	4.68	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.257269 °	38.247720 °
				-121.738446 °	-121.711769 °
DWR ID	DWR_RD0536_01_s_2014_61				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

LM Start	2.56	Rating **	M	Issue No.	31
LM End	2.68	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.256964 °	38.255321 °
				-121.738473 °	-121.738085 °
DWR ID	DWR_RD0536_01_f_2012_31				
Action/Comments					
Add appropriate gravel or road base. Grade and compact.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.74	Rating **	M	Issue No.	62
LM End	2.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.254927 °	38.254927 °
				-121.737139 °	-121.737138 °
DWR ID	DWR_RD0536_01_s_2014_62				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	2.79	Rating **	M	Issue No.	58
LM End	2.83	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.255025 °	38.255257 °
				-121.736172 °	-121.735400 °
DWR ID	DWR_RD0536_01_f_2014_58				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	2.95	Rating **	M	Issue No.	63
LM End	2.95	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.256098 °	38.256098 °
				-121.733720 °	-121.733720 °
DWR ID	DWR_RD0536_01_s_2014_63				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	3.67	Rating **	U	Issue No.	68
LM End	3.67	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.252655 °	38.252655 °
				-121.726442 °	-121.726442 °
DWR ID	DWR_RD0536_01_f_2014_68				
Action/Comments					
Inspector Comments: No picture taken.					

No Photos

LM Start	3.68	Rating **	U	Issue No.	36
LM End	3.68	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Repair Gates			38.252578 °	38.252578 °
				-121.726439 °	-121.726439 °
DWR ID	DWR_RD0536_01_s_2012_36				
Action/Comments					
Inspector Comments: This gate need to be repaired.					

Photo 1 of 1 : FA_2014_RD0536_208_36_20141030_00004.jpg



Repair this gate. Someone could get hurt trying to open and close this gate. No new picture was taken, no change to this gate. 09-04-2014.

LM Start	3.93	Rating **	M	Issue No.	32
LM End	4.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.250728 °	38.249578 °
				-121.722992 °	-121.718768 °
DWR ID	DWR_RD0536_01_f_2012_32				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	4.63	Rating **	U	Issue No.	69
LM End	4.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.248297 °	38.248002 °
				-121.712055 °	-121.711892 °
DWR ID	DWR_RD0536_01_f_2014_69				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the wild Arundo from the waterward levee slope.					

Photo 1 of 1 : FA_2014_RD0536_208_69_20141107_00027.jpg



Unsatisfactory growth of Arundo present on waterward levee section.

LM Start	4.94	Rating **	M	Issue No.	16
LM End	4.96	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.245581 °	38.245667 °
				-121.708605 °	-121.708327 °
DWR ID	DWR_RD0536_01_f_2014_16				
Action/Comments					
Inspector Comments: 2011 - Multiple erosion pockets from tree popouts. A smaller erosion pocket in the middle of a failing bank repair. Pump structure at the downstream end may be contributing to the erosion. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: LDS_0-8_R]					

No Photos

LM Start	5.00	Rating **	M	Issue No.	15
LM End	5.03	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.245981 °	38.246326 °
				-121.707609 °	-121.706737 °
DWR ID	DWR_RD0536_01_f_2014_15				
Action/Comments					
Inspector Comments: 2011 - Levee toe is unraveling with large slumping sections. This site is downstream of old bank rock. 2012 - Erosion pocket has increased in size. 2013: Site is part of the extended inventory, last inspected 2011. [2013 Site ID: LDS_0-7_R]					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	5.17	Rating **	U	Issue No.	65
LM End	5.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245300 °	38.245653 °
				-121.704909 °	-121.702569 °
DWR ID	DWR_RD0536_01_s_2014_65				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: These young oak trees need to be removed from the landward slope and shoulder before they get any larger.					

Photo 1 of 1 : FA_2014_RD0536_208_65_20141030_00007.jpg



Looking downstream from levee mile 5.17 to 5.31 at unsatisfactory woody tree growth on landside levee slope and shoulder.

LM Start	5.17	Rating **	M	Issue No.	42
LM End	5.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245333 °	38.245413 °
				-121.704724 °	-121.697309 °
DWR ID	DWR_RD0536_01_f_2012_42				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	5.21	Rating **	M	Issue No.	29
LM End	5.40	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245339 °	38.245786 °
				-121.704304 °	-121.700859 °
DWR ID	DWR_RD0536_01_s_2012_29				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.58	11/05/2014 11/05/2014	Herman Phillips

LM Start	5.39	Rating **	M	Issue No.	5
LM End	5.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245602 °	38.245628 °
				-121.702037 °	-121.700970 °
DWR ID	DWR_RD0536_01_s_2012_5				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	5.46	Rating **	U	Issue No.	70
LM End	5.58	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.245608 °	38.245610 °
				-121.699768 °	-121.697493 °
DWR ID	DWR_RD0536_01_f_2014_70				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: District need to remove the wild growth from the waterward levee slope and shoulder.					

Photo 1 of 1 : FA_2014_RD0536_208_70_20141107_00028.jpg



Unsatisfactory growth of young trees present on waterside levee shoulder and slope.

*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	5.01	11/05/2014 11/05/2014	Herman Phillips

LM Start	0.01	Rating **	M	Issue No.	5
LM End	0.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.244240 °	38.243630 °
				-121.696830 °	-121.696470 °
DWR ID	DWR_RD0536_02_s_2012_5				
Action/Comments					
Equipment					
Inspector Comments: Equipment within the 10-foot easement looking from levee mile 0.06 back towards 0.01.					

Photo 1 of 1 : FA_2014_RD0536_209_5_20141008_00001.jpg



Unauthorized encroachment on the landward side within 10-foot of the levee toe, looking back upstream. No new picture, no change with this issue.

LM Start	0.02	Rating **	U	Issue No.	17
LM End	0.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.244225 °	38.244225 °
				-121.696980 °	-121.696980 °
DWR ID	DWR_RD0536_02_s_2014_17				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the tall weeds present at the gate landside of levee.					

Photo 1 of 1 : FA_2014_RD0536_209_17_20141112_00009.jpg



Tall weeds present at gate on the landside slope.

LM Start	0.04	Rating **	C	Issue No.	1
LM End	2.09	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.243813 °	38.214528 °
				-121.696933 °	-121.693788 °
DWR ID	DWR_RD0536_02_s_2012_1				
Action/Comments					
Repair depressions or ruts in the crown or slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	5.01	11/05/2014 11/05/2014	Herman Phillips

LM Start	0.04	Rating **	C	Issue No.	18
LM End	2.11	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.243894 °	38.214578 °
				-121.696919 °	-121.693953 °
DWR ID	DWR_RD0536_02_s_2014_18				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

LM Start	0.77	Rating **	M	Issue No.	16
LM End	2.15	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.233467 °	38.214050 °
				-121.698007 °	-121.693725 °
DWR ID	DWR_RD0536_02_f_2012_16				
Action/Comments					
Add appropriate gravel or road base. Grade and compact.					

No Photos

LM Start	1.09	Rating **	M	Issue No.	2
LM End	1.15	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.228881 °	38.227928 °
				-121.697754 °	-121.697621 °
DWR ID	DWR_RD0536_02_s_2012_2				
Action/Comments					
Repair depressions or ruts in the crown or slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	5.01	11/05/2014 11/05/2014	Herman Phillips

LM Start	1.40	Rating **	M	Issue No.	9
LM End	1.40	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.224382 °	38.224382 °
				-121.697050 °	-121.697050 °
DWR ID	DWR_RD0536_02_f_2014_9				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	2.10	Rating **	M	Issue No.	14
LM End	2.98	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.214666 °	38.203122 °
				-121.693969 °	-121.687179 °
DWR ID	DWR_RD0536_02_s_2012_14				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	2.11	Rating **	M	Issue No.	24
LM End	3.40	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.214579 °	38.197754 °
				-121.693953 °	-121.683742 °
DWR ID	DWR_RD0536_02_s_2014_24				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	5.01	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.53	Rating **	U	Issue No.	12
LM End	4.34	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.208848 °	38.196775 °
				-121.691115 °	-121.699223 °
DWR ID	DWR_RD0536_02_f_2014_12				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Dead weeds present on the landward slope need to be removed.					

Photo 1 of 1 : FA_2014_RD0536_209_12_20141112_00013.jpg



Dead tall weeds present on the landward slope.

LM Start	2.53	Rating **	U	Issue No.	13
LM End	4.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.208848 °	38.196775 °
				-121.691115 °	-121.699223 °
DWR ID	DWR_RD0536_02_f_2014_13				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Control the tall weeds from the levee section waterward.					

Photo 1 of 1 : FA_2014_RD0536_209_13_20141112_00012.jpg



Unwanted tall weeds present on the waterward levee slope.

LM Start	2.56	Rating **	M	Issue No.	21
LM End	3.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.208572 °	38.197429 °
				-121.690870 °	-121.683666 °
DWR ID	DWR_RD0536_02_s_2013_21				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Reclamation District No. 0536 Egbert

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	5.01	11/05/2014 11/05/2014	Herman Phillips

LM Start	2.76	Rating **	M	Issue No.	25
LM End	3.31	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.205944 °	38.199012 °
				-121.689174 °	-121.684186 °
DWR ID	DWR_RD0536_02_s_2013_25				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	3.69	Rating **	M	Issue No.	10
LM End	3.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.196982 °	38.196850 °
				-121.688350 °	-121.688542 °
DWR ID	DWR_RD0536_02_s_2012_10				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					

No Photos

LM Start	3.74	Rating **	M	Issue No.	3
LM End	3.75	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.196881 °	38.196871 °
				-121.689038 °	-121.689220 °
DWR ID	DWR_RD0536_02_s_2013_3				
Action/Comments					
Add appropriate material and re-grade the levee to bring the crown above the design elevation.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---